

1. Security Classification of this Page : **Restricted**

2. Type of Document **Project Document**

3. Report No. : 4. Date : 5. Security Classification/
PD MT 8523 : Aug. 1985 : Declassification Schedule
: : **Restricted**

6. Title/Sub-title

Failure of the Stabiliser Spar Tube of a Chetak Helicopter

7. Author(s)

A.C.Raghuram, S.Radhakrishnan, R.V.Krishnan and V.Ramachandran

8. Division/Section : 9. Project No.
Materials Science : **MT-001**

10. Type of report/ : 11. pages [2] : 12. Approved by/
Period covered : tables [] : No. of copies
Failure Analysis : illustrations [3] : **A.K.Singh**
: : **12**

13. a) Sponsoring Agency(s) : 13. b) Participating Agency(s)
: **Chief Resident Engineer**
: **(Helicopters), Dte. of**
: **Aeronautics**

14. Keywords

**Stabiliser spar tube, Helicopter, Weld penetration,
Fatigue failure**

15. Abstract

Failure of the stabiliser spar tube of a Chetak helicopter was analysed. The failure had occurred at a welded junction. Incomplete fusion during welding has been responsible for the initiation and propagation of a fatigue crack. The final fracture was by overload.